


	A	B	C	D
1/4"	43	8	47,5	10
3/8"	45,5	10	51	10,5
1/2"	50	15	55	12
3/4"	56,5	20	71	12,5
1"	66	25	78,5	14
1 1/4"	78,5	32	97	16





Equazione Caratteristica		Cv	KV	kv
misura 1/4" =	$1.1 \cdot 10^{-4} G^{1.9607}$	4,0	3,5	59,0
misura 3/8" =	$3 \cdot 10^{-5} G^{1.864}$	11,4	10,9	181,0
misura 1/2" =	$10^{-4} G^{1.8666}$	20,3	19,3	321,9
misura 3/4" =	$1.6 \cdot 10^{-6} G^{1.8968}$	46,6	43,4	722,9
misura 1" =	$6 \cdot 10^{-7} G^{1.9261}$	67,4	61,4	1022,6
misura 1 1/4" =	$2.4 \cdot 10^{-7} G^{1.8991}$	125,2	116,3	1937,7

, bar

