


	A	B	C	D
3/8"	56,5	10	51	10,5
1/2"	61,5	15	55	12
3/4"	68	20	71	12,5
1"	79	25	78,5	14
1 1/4"	92,5	32	97	16





Equazione Caratteristica

misura 3/8" = $3 \cdot 10^{-5} G^{1.864}$

misura 1/2" = $10^{-4} G^{1.8666}$

misura 3/4" = $1.6 \cdot 10^{-6} G^{1.8968}$

misura 1" = $6 \cdot 10^{-7} G^{1.9261}$

misura 1"1/4 = $2.4 \cdot 10^{-7} G^{1.8991}$

	Cv	KV	kv		Cv	KV	kv
misura 3/8" =	11,4	10,9	181,0	misura 1" =	67,4	61,4	1022,6
misura 1/2" =	20,3	19,3	321,9	misura 1"1/4 =	125,2	116,3	1937,7
misura 3/4" =	46,6	43,4	722,9				

, bar

